


NPA - PREVIEW ALL UNITS

ITEM# 1120A

2006 SUZUKI M109RK6



VEHICLE DETAILS

Item #	1120A
Year	2006
Make	SUZUKI
Model	M109RK6
VIN	JS1VY53A062101658
Color	SILVER
Miles / Hours	26632
Documents	TX TITLE
Location	Dallas
Clean Wholesale	\$3,985
Vehicle Auction Notes	MILEAGE EXEMPT ON TITLE

CONDITION REPORT

ENGINE MECHANICAL	8	RUNS/INTERNAL WEAR
FRAME MOTORCYCLE	8	COSMETIC BOTTOM FRAME
TRANSMISSION M/C	4	INOP/UNABLE TO TEST - MECHANICAL ISSUE
ENGINE COSMETIC	7	COSMETIC HEAVY
FUEL TANK M/C	6	DENTED
FAIRING/UPPER	-	Not Rated
SUSPENSION/FRONT	7	SEAL LEAK
SUSPENSION/REAR	8	COSMETIC LIGHT
LUGGAGE	-	Not Rated
FENDER/FRONT	5	COSMETIC DAMAGE
FENDER/REAR	7	COSMETIC HEAVY
FAIRING/LEFT	8	COSMETIC LIGHT
FAIRING/RIGHT	8	COSMETIC LIGHT
FINAL DRIVE	6	MECHANICAL ISSUE - INOPERABLE
EXHAUST M/C	7	MISSING/DAMAGED SHIELDS
WHEEL/FRONT MC	8	COSMETIC LIGHT
WHEEL/REAR MC	8	COSMETIC LIGHT
CONTROLS/HAND	7	GRIPS RIPPED/TORN
STEERING M/C	8	COSMETIC LIGHT
FUEL TANK COVER/SHROUDS	8	COSMETIC LIGHT
CONTROLS/FOOT	8	COSMETIC LIGHT
BRAKES/FRONT	5	VISUALLY COMPLETE/CANNOT VERIFY
BRAKES/REAR	5	VISUALLY COMPLETE/CANNOT VERIFY
WINDSHIELD MC	-	Not Rated
SIDE COVERS M/C	8	COSMETIC LIGHT
TIRE/FRONT CRUISER	4	WORN 2/32 OR LESS
TIRE/REAR CRUISER	4	WORN 2/32 OR 1/32
ELECTRONICS	-	Not Rated



GAUGES/OIL/VOLT	-	Not Rated
LIGHTS M/C	8	COSMETIC LIGHT
SEAT M/C	8	COSMETIC
GAUGES ODO M/C	4	CANNOT VERIFY
FOOT RESTS	8	COSMETIC LIGHT
MIRRORS	7	COSMETIC HEAVY
TURN SIGNALS	5	2 MISSING/DAMAGED
STAND	8	COSMETIC LIGHT
IGNITION SWITCH	9	GOOD
BATTERY	9	BATTERY WORKS