

NPA - PREVIEW ALL UNITS

ITEM# 1121

2007 YAMAHA XVZ13CTW/C RYL STR TR DLX



















VEHICLE DETAILS

Item #	1121
Year	2007
Make	YAMAHA
Model	XVZ13CTW/C RYL STR TR DLX
VIN	JYAVP18EX7A005200
Color	RED
Miles / Hours	11737
Documents	FL TITLE
Location	Atlanta
Clean Wholesale	\$4,215
Vehicle Auction Notes	N/A

CONDITION REPORT

CONDITION REPORT = 71 (Total) 79 (Mechanical) / 67 (Cosmetic)

ENGINE - MECHANICAL	9	OPERATES NORMAL
FRAME - CRUISER	7	COSMETIC HEAVY
TRANSMISSION	9	OPERATES NORMAL
ENGINE/TRANSMISSION COSMETIC	7	COSMETIC HEAVY
FAIRING/UPPER	-	Not Rated

FUEL TANK	5	COSMETIC DAMAGE - DENTED		
SUSPENSION/FRONT	7	COSMETIC HEAVY		
SUSPENSION/REAR	8	COSMETIC LIGHT		
FAIRING/LEFT	7	COSMETIC HEAVY		
FAIRING/RIGHT	7	COSMETIC HEAVY		
FENDER/FRONT	7	COSMETIC HEAVY		
FENDER/REAR	7	COSMETIC HEAVY		
LUGGAGE	7	COSMETIC HEAVY		
REVERSE	-	Not Rated		
EXHAUST SYSTEM	7	COSMETIC HEAVY		
FINAL DRIVE	8	LIGHT WEAR		
WHEEL(S)/FRONT	7	COSMETIC HEAVY		
WHEEL(S)/REAR	7	COSMETIC HEAVY		
CONTROLS/FOOT	7	HEAVY WEAR		
CONTROLS/HAND	7	HEAVY WEAR		
FUEL TANK COVER/TRIM PIECES	7	COSMETIC HEAVY		
SHOCK(S)/REAR	7	COSMETIC HEAVY		
STEERING	7	COSMETIC HEAVY		
BRAKES/FRONT	8	LIGHT WEAR		
BRAKES/REAR	7	HEAVY WEAR		
WINDSHIELD	0	MISSING		
ELECTRONICS	-	Not Rated		
SIDE COVERS	7	COSMETIC HEAVY		
TIRE/FRONT - CRUISER	1	CRACKED		
TIRE/REAR - CRUISER	1	CRACKED		

FOOT RESTS	7	HEAVY WEAR
GAUGES/ODOMETER	8	COSMETIC LIGHT
GAUGES/OIL/VOLT	-	Not Rated
LIGHTS	5	COSMETIC DAMAGE - TAIL LIGHT CRACKED
SEAT(S)	7	STAINED/FADED
MIRRORS	8	COSMETIC LIGHT
TURN SIGNALS	8	COSMETIC LIGHT
BATTERY	9	BATTERY WORKS
IGNITION SWITCH	9	OPERATIONAL/HAS KEY
STAND	7	HEAVY WEAR
STARTS/RUNS	9	YES

